

Product Obsolescence: 3500 Series, Molded RF Coil

Description of Change: Delevan announces a obsolescence of it's 3500 Series a DLA approved product, qualified to MIL-PRF-15305. Supply Base closure and low market demand has lead to the decision to remove this product offering.

Delevan P/N:

OBSOLETE PART NUMBER	DESCRIPTION	Qualified Product Listing Part Number
3500-00K	MS75052--1, Through Hole, Molded RF Coil, 47 uH , +/- 10%	MS75052-1
3500-02K	MS75052--2, Through Hole, Molded RF Coil, 56 uH , +/- 10%	MS75052-2
3500-04K	MS14047--1, Through Hole, Molded RF Coil, 68 uH , +/- 10%	MS14047-1
3500-06K	MS14047--2, Through Hole, Molded RF Coil, 82 uH , +/- 10%	MS14047-2
3500-08K	MS14047--3, Through Hole, Molded RF Coil, 100 uH , +/- 10%	MS14047-3
3500-10K	MS14047--4, Through Hole, Molded RF Coil, 120 uH , +/- 10%	MS14047-4
3500-12K	MS14047--5, Through Hole, Molded RF Coil, 150 uH , +/- 10%	MS14047-5
3500-14K	MS14048--1, Through Hole, Molded RF Coil, 180 uH , +/- 10%	MS14048-1
3500-16K	MS14048--2, Through Hole, Molded RF Coil, 220 uH , +/- 10%	MS14048-2
3500-18K	MS14048--3, Through Hole, Molded RF Coil, 270 uH , +/- 10%	MS14048-3
3500-20K	MS14048--4, Through Hole, Molded RF Coil, 330 uH , +/- 10%	MS14048-4
3500-22K	MS14048--5, Through Hole, Molded RF Coil, 390 uH , +/- 10%	MS14048-5

Delevan Product Series: 3500

Effectivity Date: 10/25/2024

Product Classification: Through Hole, Molded RF Coil

Replacement Series: None

Expected Effect on Quality/Reliability/Performance: N/A

Implementation Date: Limited last time buy offered till April 28th, 2025 or as limited product inventory is available.

Issued By: Delevan, Product Line Management

Contact Information:

Delevan

270 Quaker Road, East Aurora, NY 14052

Phone: 716.652.3600

Email:

Sean.Anderson@regalrexnord.com

www.delevan.com